

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
11/10/2021	1131 Ridgeview Lane	Need to unclog pipe	0.5	13891	12/15/2021
	1151 Creekstone Lane	Pipe goes under foundation of house?		14071	1/19/2022
	1010 Creekstone Lane	Curb need repairing		14072	1/19/2022

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'10.85987" - W83°28'10.71157Location: 1030 Ridgeview Ln. Bishop, GA. 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.22646" - W 83° 28' 12.26778Location: 1061 Ridgeview Ln., Bishop GA 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.26685" - W 83° 28' 12.75741Location: 1050 Ridgeview Ln., Bishop GA. 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 8.13983" - W 83° 28' 17.12755"Location: 1090 Ridgeview Ln, Bishop, GA, 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 8.13162" - W 83° 28' 17.16258"Location: 1091 Ridgeview Ln, Bishop, GA, 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'5.89570" - W83°28'18.72075"Location: 1131 Ridgeview, Bishop, GA 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33°50'4.80680" - W 83°28'19.75363"Location: 1151 Ridgeview Ln, Bishop GA 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'5.36867" - W83°28'19.59494"Location: 1120 Ridgeview Ln. Bishop, GA 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'4.95039" - W83°28'20.05783"Location: 1131 Ridgeview Ln, Bishop, GA, 30621 (6)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	Need to unclog pipe.

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request																				
13891	Road Department	Michael Weathers		12/15/2021	7:30 AM																				
<b>Location of Request</b>																									
1131 Ridgeview Lane																									
Task	Date Completed																								
Pipe Cleaning	12/15/2021																								
Action for Task	Date of Action																								
removed 1/2 ton of silt and debris from pipe	12/15/2021																								
<table border="1"> <thead> <tr> <th>Employee Hours and Cost</th> <th># of Employees</th> <th>Combined Hours</th> <th>Cost of Action</th> </tr> </thead> <tbody> <tr> <td></td> <td>4</td> <td>4.00</td> <td></td> </tr> </tbody> </table>						Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action		4	4.00													
Employee Hours and Cost	# of Employees	Combined Hours	Cost of Action																						
	4	4.00																							
<b>Subcontractor Hours and Cost</b>																									
<table border="1"> <thead> <tr> <th>Equipment Hours and Cost</th> <th>Equipment</th> <th>Hours</th> <th>Equip Cost</th> </tr> </thead> <tbody> <tr> <td></td> <td>D146 FORD</td> <td>1.00</td> <td></td> </tr> <tr> <td></td> <td>D321 CAT EXCAVATOR</td> <td>1.00</td> <td></td> </tr> <tr> <td></td> <td>D494 DUMP TRUCK</td> <td>1.00</td> <td></td> </tr> <tr> <td></td> <td>G489 FORD</td> <td>1.00</td> <td></td> </tr> </tbody> </table>						Equipment Hours and Cost	Equipment	Hours	Equip Cost		D146 FORD	1.00			D321 CAT EXCAVATOR	1.00			D494 DUMP TRUCK	1.00			G489 FORD	1.00	
Equipment Hours and Cost	Equipment	Hours	Equip Cost																						
	D146 FORD	1.00																							
	D321 CAT EXCAVATOR	1.00																							
	D494 DUMP TRUCK	1.00																							
	G489 FORD	1.00																							
<b>Materials Cost</b>																									
Employee Costs for this Task:	\$0.00																								
Subcontractor Costs for this Task:	\$0.00																								
Equipment Costs for this Task:	\$0.00																								
Materials Costs for this Task:	\$0.00																								
<table border="1"> <tr> <td>Total All Employee Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Subcontractor Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Equipment Costs:</td> <td>\$0.00</td> </tr> <tr> <td>Total All Materials Costs:</td> <td>\$0.00</td> </tr> <tr> <td><b>GRAND TOTAL:</b></td> <td><b>\$0.00</b></td> </tr> </table>						Total All Employee Costs:	\$0.00	Total All Subcontractor Costs:	\$0.00	Total All Equipment Costs:	\$0.00	Total All Materials Costs:	\$0.00	<b>GRAND TOTAL:</b>	<b>\$0.00</b>										
Total All Employee Costs:	\$0.00																								
Total All Subcontractor Costs:	\$0.00																								
Total All Equipment Costs:	\$0.00																								
Total All Materials Costs:	\$0.00																								
<b>GRAND TOTAL:</b>	<b>\$0.00</b>																								

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33°50'11.82190" - W 83°28'5.17942Location: 1031 Spring Creek Dr. Bishop GA. 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'12.07783" - W83°28'5.7783"Location: Spring Creek Dr. Bishop GA 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.06255" - W 83° 28' 3.80418"Location: 1000-1032 Spring Creek Dr. Bishop, 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.15698" - W 83° 27' 52.15789"Location: 1120 Creekstone Ln, Bishop GA. 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.09287" - W 83° 27' 52.56909"Location: 1151 Creekstone Ln, Bishop GA 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Trash or debris at inlet opening	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input type="radio"/> No <input checked="" type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input type="radio"/> No <input checked="" type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 50' 10.93641 - W 83° 27' 52.16611"Location: 1151 Creekstone Ln Bishop GA 30621 (C)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

Pipe goes under foundation of House?

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14071	Road Department	Michael Weathers		1/19/2022	7:30 AM

**Location of Request**

1151 Creekstone Lane

**Task**
**Date Completed**

1/19/2022

Drainage problem

**Action for Task**
**Date of Action**

inspected, pipe runs to rear of property to cat

1/19/2022

Employee Hours and Cost
# of Employees
Combined Hours
Cost of Action

1

1.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

G489 FORD

1.00

Materials Cost

**Employee Costs for this Task:** \$0.00

**Subcontractor Costs for this Task:** \$0.00

**Equipment Costs for this Task:** \$0.00

**Materials Costs for this Task:** \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°50'10.65057" - W83°27'51.47470"  
Location: 1164-1198 Creekstone Ln. Bishop GA 30621 (D)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33°49'58.39044" - W 83°27'58.93728"Location: 1021 Creekstone Ln, Bishop GA 30621 (A)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 58.18550" - W 83° 27' 58.65426"Location: 1010 Creekstone Ln, Bishop GA 30621 (B)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 57.90041" - W 83° 27' 58.44106"Location: 1010 Creekstone Ln, Bishop, 30621 (C)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 57.83658" - W 83° 27' 58.03266"Location: 1010 Creekstone Ln., Bishop GA 30621 (D)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 57.46 S 83° 27' 58.18636 WLocation: 1110 Spring Lake Dr., Bishop, GA 30621 (E)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 19' 57.16258" - W 83° 27' 57.81766"  
Location: 1130 Spring Lake Dr. Bishop GA 30621 (F)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 56.961 06" - W 83° 27' 57.049 70"Location: 1010 Creekstone Ln, Bishop GA 30621 (G)

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	<i>Curb needs repairing</i>
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
14072	Road Department	Michael Weathers		1/19/2022	7:30 AM

**Location of Request**

1010 Creekstone Lane

**Task**

Curb + Gutter Repair

**Date Completed**

1/19/2022

**Date of Action**

1/19/2022

**Action for Task**

inspected curbing, will repair when needed, n

Employee Hours and Cost
# of Employees
Combined Hours
Cost of Action

1

1.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

G489 FORD

1.00

Materials Cost

**Employee Costs for this Task:** \$0.00

**Subcontractor Costs for this Task:** \$0.00

**Equipment Costs for this Task:** \$0.00

**Materials Costs for this Task:** \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/Description

GPS Point Name: 1033°49'51.57716"-W83°27'56.52675"  
Location: 1171 Spring Lake Dr. Bishop, GA 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°49'50.85386" - W83°27'57.80512"Location: 1170 Spring Lake Dr., Bishop GA 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**CATCH BASIN INSPECTION CHECKLIST**Date: 11-10-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 49' 50.32014" - W 83° 27' 57.30420"Location: 1191 Spring Lake Dr. Bishop GA 30621

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	