

DATE	LOCATION	WORK TO BE DONE	TONS	WORK ORDER #	DATE COMPLETED
12/3/2021	1611 Pete Dickens Road	Pipe needs to be backfilled with dirt		13911	12/15/2021
	1161 Scarlet Oak Circle	Structure needs silt removed		13977	12/22/2021

## DITCH INSPECTION CHECKLIST

Date: 12-3-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°55'44.85" W83°33'17.16841"

Location: 12410 Minut Creek Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'45.82229"-W83°33'11.40896"Location: 1272 McNutt Creek Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'45.72350"-W83°33'11.47402"Location: 1300 Mr. Nutt Creek Rd.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'46.79164"-W83°33'8.30541"Location: 1320 McNutt Creek Rd., Bogat GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'49.97737"-W83°33'5.35540"Location: 1361 McNutt Creek Rd., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'51.30238"-W83°33'4.11302"Location: 1360 McNutt Creek Rd, Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William R. LodesLocation/DescriptionID #: N33°55.36633" - W83°33'1.47476"Location: 1425 McNutt Creek Rd., Bogat GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°56'1.99983"-W83°32'40.25213"Location: 1611 McNutt Creek Rd., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°56'2.00068"-W83°32'37.21075"Location: 1681 McNutt Creek Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°56'3.26418"-W83°32'30.28701"Location: 1710 McNutt, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°56'4.22192" - W83°32'28.25676"Location: 1730 McNutt Creek Rd., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB)

**CATCH BASIN INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°55'3.17612" - W83°33'1.28807"Location: 1001 Garland Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

(CB2)

**CATCH BASIN INSPECTION CHECKLIST**

Date: 12-3-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°55'3.53912" - W83°33'1.08993"

Location: 1000 Garland Dr., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

## DITCH INSPECTION CHECKLIST

Date: 12-3-2021

Inspector(s): William Rhodes

### Location/Description

ID #: N33°55'3.23306"-W83°33'0.32114"

Location: 1010 Pete Dickens Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'12.66431"-W83°32'59.04408"Location: 1100 Pete Dickens Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'14.25693"-W83°32'58.20690"Location: 1110 Pete Dickens Rd., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 55' 16.20820" - W 83° 32' 57.80588"Location: 1181 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2020Inspector(s): William RhodesLocation/DescriptionID #: N33°55'19.42264"-W83°32'56.28763"Location: 1183 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'20.39210"-W83°32'55.1673"Location: 1200 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'22.06431"-L83°32'54.07263"Location: 1250 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'23.11891"-W83°32'53.78365"Location: 1241 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'23.34452"-W83°32'53.14441"Location: 1260 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'26.50882"-W83°32'51.10324"Location: 1270 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'26.30270"-W83°32'51.32883"Location: 1291 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'32.67360"-W83°32'47.70182"Location: 1350 Pete Dickens Rd., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'35.26204"-W83°32'47.08474"Location: 1010 Cobblestone Dr., Bogart, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'35.90613"-W83°32'46.57312Location: 1378 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'44.85991"-W83°32'44.90242"Location: 1451 Pete Dickens Rd. Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'46.55927"-W83°32'44.70362"Location: 1504 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'47.26337"-W83°32'44.76132"Location: 1530 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N 33° 55' 49.28805" - W 83° 32' 45.94507"Location: 1541 Pete Dickens Rd., Bogart GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'51.07667"-W83°32'46.53641"Location: 1541 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'52.16" W83°32'47.05"220"Location: 1561 Pete Dickins Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Vegetation maintained to capture sediment	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Debris (litter, branches, brush, etc.)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Excessive siltation buildup	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes/Cross Culverts (clogged or damaged)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'52.97804"-W83°32'47.46538"Location: 1571 Pete Dickens Rd., Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	

**DITCH INSPECTION CHECKLIST**Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionID #: N33°55'55.82926"-W83°32'48.66561"Location: 1611 Pete Dickens Rd, Bogart GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Proper slope	Yes / <input checked="" type="radio"/> No	
Vegetation maintained to capture sediment	Yes / <input checked="" type="radio"/> No	
Debris (litter, branches, brush, etc.)	Yes / <input checked="" type="radio"/> No	
Excessive siltation buildup	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes/Cross Culverts (clogged or damaged)	Yes / <input checked="" type="radio"/> No	Pipe need to back filled with dirt.

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13911	Road Department	Michael Weathers		12/15/2021	7:30 AM

**Location of Request**

1611 Pete Dickens Rd

**Task**

Pipe Repair

**Date Completed**

12/15/2021

**Action for Task**

backfilled around end of pipe

**Date of Action**

12/15/2021

Employee Hours and Cost
# of Employees   Combined Hours   Cost of Action

4                    8.00

Subcontractor Hours and Cost

Equipment Hours and Cost	Equipment	Hours	Equip Cost
	D146 FORD	2.00	
	D321 CAT EXCAVATOR	2.00	
	D494 DUMP TRUCK	2.00	
	G489 FORD	2.00	

Materials Cost	Material Name	Amount Used (Units)	Measured In	Material Cost
	Dirt	3.00	Ton	

**Employee Costs for this Task:**                    \$0.00

**Subcontractor Costs for this Task:**                    \$0.00

**Equipment Costs for this Task:**                    \$0.00

**Materials Costs for this Task:**                    \$0.00

**Total All Employee Costs:**                    \$0.00

**Total All Subcontractor Costs:**                    \$0.00

**Total All Equipment Costs:**                    \$0.00

**Total All Materials Costs:**                    \$0.00

**GRAND TOTAL:**    \$0.00

**CATCH BASIN INSPECTION CHECKLIST**

(CB1)

Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N33°53'46.99299" - W83°26'17.64809"Location: 1039 Magnolia Dr., Athens GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / No	
"No dumping" educational marker	Yes / No	
Trash or debris at inlet opening	Yes / No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / No	
Pipes (roots, damaged, flow impeded)	Yes / No	

**CATCH BASIN INSPECTION CHECKLIST**

(CB2)

Date: 12-3-2021Inspector(s): William RhodesLocation/DescriptionGPS Point Name: N 33° 53' 46.74439" - W 83° 26' 17.63046"Location: 1099 Magnolia Dr, Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(CB3)

**CATCH BASIN INSPECTION CHECKLIST**

Date: 12-3-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'46.68520"-W83°26'17.41125"

Location: 1099 Magnolia Dr., Athens GA

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

**CATCH BASIN INSPECTION CHECKLIST**

(CB4)

Date: 12-3-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'47.77" W83°26'15.21344"

Location: 1170 Scarlet Oak Cir., Athens GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes / <input checked="" type="radio"/> No	
"No dumping" educational marker	Yes / <input checked="" type="radio"/> No	
Trash or debris at inlet opening	Yes / <input checked="" type="radio"/> No	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes / <input checked="" type="radio"/> No	
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes / <input checked="" type="radio"/> No	
Pipes (roots, damaged, flow impeded)	Yes / <input checked="" type="radio"/> No	

(CBS)

**CATCH BASIN INSPECTION CHECKLIST**

Date: 12-3-2021

Inspector(s): William Rhodes

Location/Description

GPS Point Name: N33°53'47.93807" - W83°26'14.86628"

Location: 1161 Scarlet Oak Cir., Athens, GA.

Inspection Items	Maintenance Required?	Comments/Follow-up
Structure (damaged, settled, cracked)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
"No dumping" educational marker	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Trash or debris at inlet opening	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Sediment (cleaning required if sediment exceeds 1/3 of the sump depth)	Yes <input checked="" type="radio"/> No <input type="radio"/>	Structure need silt removed.
Contaminants or pollution (evidence of oils, grease, chemicals)	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Pipes (roots, damaged, flow impeded)	Yes <input checked="" type="radio"/> No <input type="radio"/>	

# Work Request Invoice - Public Works

WOID	Department	Name of Requestor	Daytime Phone	Date of Request	Time of Request
13977	Road Department	Michael Weathers		12/22/2021	7:30 AM

**Location of Request**

1161 Scarlet Oak Circle

**Task**

Catch Basin Cleaning

**Date Completed**

12/22/2021

**Action for Task**

removed 1 ton of silt from structure

**Date of Action**

12/22/2021

Employee Hours and Cost
# of Employees
Combined Hours
Cost of Action

4

6.00

Subcontractor Hours and Cost
Equipment Hours and Cost
Equipment
Hours
Equip Cost

D321 CAT EXCAVATOR	1.50
D494 DUMP TRUCK	1.50
G489 FORD	1.50
G771	1.50

Materials Cost

Employee Costs for this Task: \$0.00

Subcontractor Costs for this Task: \$0.00

Equipment Costs for this Task: \$0.00

Materials Costs for this Task: \$0.00

**Total All Employee Costs:** \$0.00

**Total All Subcontractor Costs:** \$0.00

**Total All Equipment Costs:** \$0.00

**Total All Materials Costs:** \$0.00

**GRAND TOTAL:** \$0.00