

TYPE	MATERIAL	INSPECT_DA	OUTFALL_TO	POINT_NAME
det-/retention pond/not quality managed	earth	03/29/2005		C03-6.M1.2-Ivywood South
det-/retention pond/not quality managed	earth	01/26/2005		C02-2.M1.2-Moss Creek
det-/retention pond/not quality managed	earth	01/26/2005		C02-2.M2.2-Moss Creek
det-/retention pond/not quality managed	earth	01/11/2005		B02-2.M1.2-Trotters Walk
det-/retention pond/not quality managed	earth	01/12/2005		B02-2.M2.2-Trotters Walk
det/ret_pond	concrete	05/04/2006		B04-6.11.M1.3-Founders Grove
det-/retention pond/not quality managed	earth	03/24/2005		C04-2.M1.2-Victoria Station
det-/retention pond/not quality managed	earth	03/02/2005		C03-3.M1.2-Summit Oaks
det-/retention pond/not quality managed	earth	03/03/2005	Unnamed Trib. to Oconee River	C04-1.M1.2-Willowynd
det-/retention pond/not quality managed	earth	03/07/2005		C04-1.M2.2-Willowynd
det-/retention pond/not quality managed	concrete	03/07/2005	Unnamed Trib. to Oconee River	C04-1.3.1-Willowynd
det-/retention pond/not quality managed	earth	03/11/2005		C04-1.M3.2-Willowynd
det/ret_pond	concrete	05/01/2006		B04-3.M1.2-Barber Creek Corporate Park
det/ret_pond	concrete	05/01/2006		B04-3.2.M1.2-Barber Creek Corporate Park
det/ret_pond	concrete	05/10/2006		C02-14.1.M1.2-Parkway Shops at Epps
det/ret_pond	metal	05/17/2006	Det/Ret. Pond	C02-16.1.M1.3-Resource Valley
det/ret_pond	metal	05/17/2006	Det/Ret. Pond	C02-16.3.1.M1.2-Resource Valley
det/ret_pond	metal	05/19/2006		C01-4.1.M1.3-Meadows at Jennings Mill
det/ret_pond	concrete	05/22/2006		C01-4.3.M1.1-Meadows at Jennings Mill
det/ret_pond	concrete	05/22/2006		C01-4.5.M1.1-Meadows at Jennings Mill
det/ret_pond	concrete	05/22/2006		C01-4.6.M1.1-Meadows at Jennings Mill
det/ret_pond	concrete	1/16/2014		C02AE-Village at Manders Crossing
det/ret_pond	earth	3/10/2014		B02X-Fern Hill
det/ret_pond	earth	3/11/2014		C02S-Pointe at Epps Bridge
det/ret_pond	earth	3/11/2014		C02-Home Depot
det/ret_pond	earth	3/11/2014		C01U-Sterling Mills
det/ret_pond	earth	3/11/2014		C01U-Sterling Mills
det/ret_pond	earth	3/11/2014		B03G-Baker's Acres
det/ret_pond	earth	3/11/2014		C027A
det/ret_pond	earth	3/21/2014		B02G-Power Ridge
det/ret_pond	earth	3/21/2014		C01AF-Meridian
det/ret_pond	earth	3/24/2014		B02N-Franklin Grove
det/ret_pond	earth	3/24/2014		B02N-Franklin Grove
det/ret_pond	earth	3/24/2014		B02U-Hampton Valley BP
det/ret_pond	earth			C01AF-Meridian
det/ret_pond	earth	3/21/2014		C01AF-Meridian
det-/retention pond/not quality managed	earth	12/4/2014		C01T-Silverleaf
det-/retention pond/not quality managed	earth	3/17/2015		C01AN-Langford Business Park (316 Professional Quarter)
det/ret_pond	earth	12/17/2014		C01J-Plaza Pkwy
det/ret_pond	earth	12/17/2014		C01J-Plaza Pkwy
det/ret_pond	earth	12/17/2014		C01J-Plaza Pkwy
det/ret_pond	earth	3/17/2015		C01Z-Pkwy Shops at Epps Bridge
det/ret_pond	earth			Kroger